

468/2010



C1

9/11/10

Ref: AO/CHN/Admn/TC/272

15<sup>th</sup> December, 2009

The Sr Dy Transport Commissioner(Taxn)  
Thiruvananthapuram

Dear Sir,


Sub: Change of location of punching Chassis No. from Long  
Member to Right side below Driver seat.- For Tata ACE family.

This is to bring to your kind notice that we have changed the punching location of chassis no. with effect from 1<sup>st</sup> December, 2009. A copy of circular No. ICG UTR 06 2009 dated 10<sup>th</sup> Dec 09 with the photographs of the new location of chassis no. i.e. Right Side below the driver seat, to this effect from our Commercial Vehicle Business Unit, Customer Service- Commercial Vehicle, Pantnagar is attached for your kind perusal and record.

You are therefore requested to issue a communication to this effect to the concerned RTOs/Jt RTOs/ARTOs etc, in the State so that the vehicles get registered without any problem on this account.

Thanking you,

Yours faithfully,  
For Tata Motors Ltd

  
VIVEK VENUGOPAL  
Area Manager - Cochin.

Encl: Cir No. ICG UTR 06 2009 dtd 10<sup>th</sup> Dec 09

**TATA MOTORS LIMITED**

3rd Floor, Tutus Towers, N.H Bypass Road, Pativattom, Cochin - 682 024  
Tel: 91 0484 6601400 / 1422, Fax: 91 0484 6601429, e-mail: srocochin@tatamotors.com  
Registered Office: Bombay House 24, Homi Mody Street, Mumbai - 400 001

TATA Motors  
Commercial vehicle Business unit  
Customer Service-Commercial vehicles  
Pantnagar

---

ICG UTR 06 2009

Internal circular- G

10<sup>th</sup> Dec 2009

---

All ASO  
All Regional Service Manager,  
All Regional Managers – Customer Care

**SUBJECT:** Chassis no.punching location change from long member to the right side below driver seat.

This is to inform you that, we have changed the .punching location of chassis no with effect from 1<sup>st</sup> Dec.2009

Earlier it was punched on Chassis long member, now it has been changed to right side below driver sheet for communization for all ACE family for domestic as well as for export.

We are showing the photographs of new location of chassis no i.e. Right side below the driver seat



Chassis no.punching location  
(Right side below driver seat)

~~Encl No - 03~~

Kindly pass on this information to all Channel Partner.

Thanking You,  
Yours faithfully,


P.R.Anand (Head Service Office -Uttarakhand)


CC

Mr.S P Joshi  
Mr.Deepak Ranade  
Mr. A K Gupta  
Mr. P.C.Sukhdeva  
Mr Deepak Kenkre

Encl. No C3/1689 TC/2010 dtd 08-01-2010

Copy forwarded to all DTCs,  
RTOs and dt RTOs for information and necessary actions.

  
For Transport Commissioner

  
08-1-10.