

2207 64
C1/13608/TC/2009

Transport Commissionerate, Kerala
Trans Towers, Thiruvananthapuram
Dated: 30/07/2009

From-

The Transport Commissioner
Thiruvananthapuram

To

All Deputy Transport Commissioners,
All Regional Transport Officers and
All Joint Regional Transport Officers

Sir,

Sub: Motor Vehicles Department-Non fitment of indicators in heavy vehicles-
Instructions issued-Reg

Ref: Government Letter No.13785/CMPGRC/SK/2009/GAD dated 15/07/2009
From Chief Minister's Public Grievance Redressal Cell in
"Sutharya Keralam"

Your attention is invited to the above subject. Rule 102 of Central Motor Vehicles Rules, 1989 defines the signalling devices, direction indicators and stop lights in all motor vehicles including construction equipment vehicles and shall fitted and maintained in the prescribed manner. A complaint had been forwarded from the Chief Minister's Public Grievance Redressal Cell through Sutharya Keralam by stating that it is a common sight that vehicles, especially heavy vehicles, are conducting operation without fitting indicators. It causes accident and it is also the violation of rules and traffic regulations. In the light of this, all the enforcement officers are directed to enforce Rule 102 of Central Motor Vehicles Rules 1989 strictly. It is also directed to conduct night checking to detect such vehicles which are not using indicators properly.

Yours faithfully

Sd/-

Senior DTC (Taxation)
For Transport Commissioner

Approved for issue


Senior Superintendent

05/08/09