

S. AANANTHAKRISHNAN IPS ADDITIONAL DIRECTOR GENERAL OF POLICE & TRANSPORT COMMISSIONER KERALA



Transport Commissionerate

Il Floor, Trans Towers, Vazhuthacaud
Thiruvananthapuram-695 014

Phone Office 0471-2333314

Dated: 13/02/2017

E-mail: tc@keralamvd.govin

No. 19/Camp/TC/2017

To

All RTO's

Sir.

Sub: Assessment of the computer facility recommending for corrective steps-Regarding.

Based on the inspection of the computer networking and hardware at various offices the following suggestions have been given by the testing team of TC office. It is instructed that necessary corrective actions be taken at all officers where such issues are existing and compliance report should be submitted in a month.

- സെർവ്വർ റാക്കിന്റെ വശങ്ങളിലെ സംരക്ഷിത പാളികൾ യഥാവിധം ക്രമീകരിക്കേണ്ടതാണ്.
- സെർവ്വർ മുറിയിൽ സൂക്ഷിച്ചിട്ടുള്ള മറ്റ് സാധന സാമഗ്രികൾ ഒഴിവാക്കുകയും പൊടിയടിച്ച് വൃത്തിയായി സൂക്ഷിക്കുകയും ചെയ്യേണ്ടതാണ്. ഹൌസ് കിപ്പിംഗ് സ്റ്റാഫ് ഇക്കാര്യം നിർവ്വഹിക്കുന്നുണ്ടെന്ന് എല്ലാ ദിവസവും എ.എസ്.എ ഉറപ്പ് വരുത്തേണ്ടതാണ്.
- KSWAN കണക്ഷനായി സെർവ്വർ മുറിയിൽ വന്നിട്ടുള്ള കേബിളുകൾ അതിനായി സ്ഥാപിച്ചിട്ടുള്ള വാൾ മൌണ്ട് റാക്കിൽ ക്രമീകരിക്കേണ്ടതാണ്.
- UPS, Battery എന്നിവ സെർവ്വർ റാക്കിനുള്ളിൽ ക്രമീകരിക്കേണ്ടതും നെറ്റ്വർക്കിൽ ബന്ധിപ്പിക്കേണ്ടതുമാണ്.
- ആഫീസിന്റെ ആവശ്യത്തിന് വാങ്ങിയ KVM സ്വിച്ച് പ്രവർത്തന ക്ഷമമാക്കേണ്ടതാണ്.
- സെർവ്വർ മുറിയിൽ താഴെപ്പറയുന്നവരുടെ ഫോൺ നമ്പരുകൾ പ്രിന്റ് ചെയ്യ് ഒട്ടിക്കേണ്ടതാണ്.
 - സി-ഡിറ്റ് ഹെൽപ്പ് ഡെസ്ക്
 - പ്രോജക്ല് മാനേജർ